

UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 27532

CSAH 123

OVER THE

CROW RIVER

DISTRICT 5 –HENNEPIN COUNTY



PREPARED FOR THE
MINNESOTA DEPARTMENT OF TRANSPORTATION

BY
COLLINS ENGINEERS, INC.

JOB NO. 3512 (CEI 110)

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure units inspected at Bridge No. 27532, Piers 1 and 2, were in good condition with no structurally significant defects observed. A portion of the footing was exposed at the downstream section of both Piers 1 and 2 with no undermining detected. A minor accumulation of timber debris was observed at the downstream section of Pier 2, and a localized scour depression was observed at the upstream end of the upstream portion of Pier 1.

INSPECTION FINDINGS:


- (A) A scour depression, 0.5 feet deep and 3 feet in radius, was observed at the upstream end of the upstream portion of Pier 1.
- (B) The footing was exposed along the north face of the downstream section of Pier 1 from the upstream nose to the downstream quarter point with up to 1 foot of vertical face exposure.
- (C) The footing was exposed for 2 feet along the south side of the upstream nose of the downstream section of Pier 2 with up to 5 inches of vertical face exposure.
- (D) A minor accumulation of timber debris, up to 6 inches in diameter, was observed at the upstream nose of the downstream portion of Pier 2.

RECOMMENDATIONS:

- (A) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.

Daniel G. Stromberg

A large, stylized handwritten signature in black ink, appearing to read 'Dan G. Stromberg', is written over a horizontal line.

Date 6/30/2004 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.

A large, stylized handwritten signature in black ink, appearing to read 'Dan G. Stromberg', is written over a horizontal line.

Daniel G. Stromberg
Registered Professional
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 27532

Feature Crossed: The Crow River

Feature Carried: CSAH 123

Location: District 5 - Hennepin County

Bridge Description: The structure consists of three spans of a concrete deck supported by multiple steel stringers. The superstructure is supported by two concrete piers and two concrete abutments. The piers are number 1 and 2 starting from the south end of the bridge.

2. INSPECTION DATA

Professional Engineer/Team Leader: Shirley M. Walker

Dive Team: Michelle D. Koerbel, Clayton G. Brookins

Date: September 28, 2002

Weather Conditions: Rain, " 50° F

Underwater Visibility: " 1 foot

Waterway Velocity: " 1.5 f.p.s.

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Piers 1 and 2.

General Shape: Piers 1 and 2 consist of two sections: an original rectangular concrete shaft with a pointed upstream nose and a rounded downstream nose that rests upon a rectangular footing/seal combination supported by concrete piles, and a newer rectangular concrete shaft with rounded noses that rests upon a rectangular footing supported by concrete piles.

Maximum Water Depth at Substructure Inspected: Approximately 9.0 feet.

4. WATERLINE DATUM

Water Level Reference: The top of the parapet at the east end of Pier 2.

Water Surface: The waterline was approximately 26.5 feet below reference.
Assumed Waterline Elevation = 73.5.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 7


Item 61: Channel and Channel Protection: Code 7

Item 92B: Underwater Inspection: Code B/09/02


Item 113: Scour Critical Bridges: Code N/02

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

_____ Yes X No



SOUNDING PLAN



GENERAL NOTES:

- Piers 1 and 2 were inspected underwater.
- At the time of inspection on September 28, 2002, the waterline was located approximately 26.5 feet below the top of the parapet at the downstream end of Pier 2. Since insufficient bridge elevation information was available a reference elevation of 100.0 was assumed. Based on the assumed reference the waterline elevation was 73.5.
- Soundings indicate the water depth at the time of inspection and are measured in feet.
- Soundings were taken parallel to the bridge at 1/4 point intervals between the substructure units.

INSPECTION NOTES:

- The channel bottom consisted of sandy gravel and 8-inch-diameter riprap with up to 4 inches of probe rod penetration.
- The channel bottom consisted of sandy gravel with up to 4 inches of probe rod penetration.
- The channel bottom consisted of riprap up to 2 feet in diameter.
- A scour depression, 0.5 feet deep and 3 feet in radius, was observed at the upstream end of Pier 1.
- The footing was exposed along the north face of the downstream section of Pier 1 with up to 1 foot of vertical face exposure.
- The footing was exposed at the upstream nose of the downstream portion of Pier 2 with up to 5 inches of vertical face exposure.
- A minor accumulation of timber debris, with pieces up to 6 inches in diameter, was observed at the upstream nose of the downstream portion of Pier 2.

Legend


- 3.8 Sounding Depth from Waterline (9/28/02)
- Timber Debris
- Scour Depression

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION


STRUCTURE NO. 27532
OVER THE CROW RIVER
DISTRICT 5, HENNEPIN COUNTY

INSPECTION AND SOUNDING PLAN

Drawn By: PRH	COLLINS ENGINEERS, INC.	Date: SEPT. 2002
Checked By: MDK	300 W. WASHINGTON, STE. 600 CHICAGO, ILLINOIS 60606 (312) 704-9300	Scale: NTS
Code: 35120110		Figure No.: 1



UPSTREAM FASCIA PROFILE



DOWNSTREAM FASCIA PROFILE

Note:
Refer to Figure 1 for General Notes.

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION		
STRUCTURE NO. 27532 OVER THE CROW RIVER DISTRICT 5, HENNEPIN COUNTY UPSTREAM AND DOWNSTREAM FASCIA PROFILES		
Drawn By: PRH Checked By: MDK Code: 35120110	COLLINS ENGINEERS, INC. 300 W. WASHINGTON, STE. 600 CHICAGO, ILLINOIS 60606 (312) 704-9300	Date: SEPT. 2002 Scale: 1"=20' Figure No.: 2



Photograph 1. Overall View of Structure, Looking Northeast.



Photograph 2. View of Pier 1, Looking Northeast.



Photograph 3. View of Pier 2, Looking South.



Photograph 4. View of New Upstream Shaft of Pier 2, Looking South.

Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 27532
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Shirley M. Walker, P.E.
WATERWAY CROSSED The Crow River

INSPECTION DATE September 28, 2002

NOTE: USE ALL APPLICABLE CONDITION
DEFINITIONS AS DEFINED IN THE MINNESOTA
RECORDING AND CODING GUIDE INCLUDING
GENERAL, SUBSTRUCTURE, CHANNEL AND
PROTECTION, AND CULVERTS AND WALL
DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE						CHANNEL					GENERAL					
			PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	Pier 1	6.5'	N	7	7	9	N	7	7	8	8	N	7	7	N	N	N	7	N
	Pier 2	9.0'	N	7	7	9	N	7	7	8	8	7	7	7	N	N	N	7	N

*UNDERWATER PORTION ONLY

REMARKS: Overall, the concrete of the piers was in good and sound condition with no structurally significant defects observed. Portions of the downstream section of both piers exhibited footing exposure with up to 1 foot of vertical exposure and no undermining detected. A minor scour depression, 0.5 foot deep and 3 feet in radius, was observed at the upstream end of Pier 1. A minor accumulation of timber debris was observed at the upstream nose of the downstream portion of Pier 2. The downstream portion of both piers exhibited small areas of concrete repair patches approximately 4 feet above the waterline.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO.
USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.